

**Characteristics:**

1. Digital LCD display
2. The indoor and outdoor temperature display at the same time
3. Choose between Celsius or Fahrenheit units pressing a key
4. Recorded daily maximum or minimum value of indoor and outdoor temperature
5. The thermometer can be hung on a wall or on the table
6. meters outdoor temperature sensor

**Temperature measurement range:**

1. Outdoor: -40 to 70 °C; -58°F to 158°F
2. Indoor: -10 °C to 50 °C; 14°F to 122°F
3. Precision is  $\pm 1^\circ\text{C}$  resolution: 0.1 °C
4. Battery: AAA Size (1.5VDC)

**Temperature measuring method:**

1. Press the MAX/MIN key to measuring the current environment of indoor and outdoor highest or lowest temperature value
2. Clear the current environment of indoor and outdoor temperature recording by pressing the RESET key.
3. Press °C / °F to select between Celsius and Fahrenheit degree.

**Características:**

1. Pantalla LCD digital
2. Muestra la temperatura interna y externa al mismo tiempo
3. Elegir entre grados Celsius y Fahrenheit pulsando un botón
4. Registra temperaturas máximas y mínimas internas y externas
5. Puede ser colgado en la pared o colocado sobre una mesa
6. Sonda de temperatura de 1.5 metros

**Rangos de temperatura:**

1. Externa: -40 to 70 °C; -58°F to 158°F
2. Interna: -10 °C to 50 °C 14°F to 122°F
3. Precisión:  $\pm 1^\circ\text{C}$  resolución: 0.1 °C
4. Pila que utiliza: 1 pila AAA 1.5VDC

**Medición de temperatura:**

1. Presione el botón MAX/MIN para medir la temperatura actual interna y externa y máxima y mínima registrada.
2. Borre las temperaturas registradas pulsando el botón RESET.
3. Presione el botón °C / °F para elegir entre grados Celsius y Fahrenheit.